






لیست ذره بین سری ۱

 <p>رده ۱ الی ۵</p> <p>8750 G (3.5X) 8775 G (2.5X) 8790 G (2.5X) 8711 G (2.5X) 8713 G (1.7X)</p>	 <p>رده ۶</p> <p>8799 G (سری کامل)</p>	 <p>رده ۷ الی ۱۰</p> <p>RH50 G (3.5X) RH75 G (2.5X) RH90 G (2.5X) RH11 G (2.5X)</p>	 <p>رده ۱۱</p> <p>RH99 G (سری کامل)</p>	 <p>رده ۱۲ الی ۱۵</p> <p>8250 G (3.5X) 8275 G (2.5X) 8290 G (2.5X) 8211 G (2.5X)</p>
 <p>رده ۱۶ الی ۱۸</p> <p>7501 GL (3X) 7501M GL (2.5X) 7501L GL (2.5X)</p>	 <p>رده ۱۹ - ۲۰</p> <p>8850 A (3X6X) 8850 G (3.5X)</p>	 <p>رده ۲۱ الی ۲۳</p> <p>1560 A (3X6X) 2125 A (2.5X5X) 3125 A (3X)</p>	 <p>رده ۲۴ الی ۲۷</p> <p>2512 G+LB (2.5X) 2513 A+LB (1.5X6X)</p>	 <p>رده ۲۸ - ۳۱</p> <p>SL30 A (10X) SL50 G (7X) SL75 G (5X)</p>
 <p>رده ۲۹ - ۳۲</p> <p>SL30R A (10X) SL50R G (7X)</p>	 <p>رده ۳۰</p> <p>SLA30 A (10X)</p>	 <p>رده ۳۴ الی ۳۷</p> <p>FD15 A (10X) FD20 A (7X) FD30 A (5X) FD40 A (5X)</p>	 <p>رده ۳۸ الی ۴۱</p> <p>FD50 G (3.5X) FD75 G (3X) FD90 G (2.5X) FD11 G (2.5X)</p>	 <p>رده ۴۲</p> <p>FDL90 G (2.5X) FDL11 G (2.5X)</p>
 <p>رده ۴۴ - ۴۵</p> <p>MP15 A (8X10X18X) MP20 A (6X8X14X)</p>	 <p>رده ۴۶</p> <p>PT35 A (3X10X)</p>	 <p>رده ۴۷</p> <p>HPL15 A (10X)</p>	 <p>رده ۴۸</p> <p>HPL30 A (10X)</p>	 <p>رده ۴۹ - ۵۰</p> <p>8920 8921</p>
 <p>رده ۵۱ - ۵۲</p> <p>CT30 A (5X) CT20 A+T (7X)</p>	 <p>رده ۵۳ الی ۵۵</p> <p>RT16 A (5X) RT17 A (2X4X) RT55 A (2X)</p>	 <p>رده ۵۶ الی ۵۹</p> <p>7703 G (3.5X) 7702 G (3X) 7701 G (2.5X) 7711 G (2.5X)</p>	 <p>رده ۶۰ - ۶۱</p> <p>SO60 A (3X) SO75 A (3X)</p>	 <p>رده ۶۲</p> <p>FHL85 G (2.5X)</p>
 <p>CE35 (3X) CE30 (5X)</p>	 <p>رده ۶۳ الی ۶۵</p> <p>CE20 (7X)</p>	 <p>رده ۶۶</p> <p>EG31 A (1.5X)</p>	 <p>رده ۶۷ - ۶۸</p> <p>SG21 GY SG21 TN</p>	 <p>رده ۶۹</p> <p>SM11 A (2X4X)</p>